



HEATING-CURING-COOLING PROCESS			
	Temperature	Time	Instructions
First stage	0 °C - 60 °C	60 minutes	Reach 60 °C
Second stage	60 °C	100 minutes	Maintain the indicated temperature for 100 minutes
Third stage (cooling)	60 °C - 0 °C	60 minutes	Decrease the temperature